

**TO BE FILLED BY THE INSPECTING OFFICER
(ASSISTANT ENGINEER)**

- 1 Name of Officer : **SONA O T**
- 2 Name of School : **SRI SAI VIDYA BHAVAN**
- 3 Location with Name of Educational District, Sub District : P Vemballur
Irinjalakuda Educational District
Kodungallur Sub District
- 4 Classification buildings as specified in Col.4 of the application for Fitness Certificate & size : Permanent
separately attached
- 5 Period for which the certificate issued : Academic year 2024-25
- 6 Nature of defect if any
- a) Foundation & basement : No
- b) Superstructure : No
- c) Doors and window : No
- d) Wood work wrought & put up : No
- e) Roof : No
- f) Flooring : No
- g) Miscellaneous (Cracks etc) : No
- 7 Any major defects noticed which will render the building unsafe : No other defects
- 8 Whether maintenance works have been done properly : Yes. Necessary safety precautions should be taken for students.
- 9 Whether the structure is sound or not for conducting classes : Sound for conducting classes under normal weather and wind conditions.

- Note: 1. The stability of the structure should be examined also with reference to location, attitude, intensity or wind, exposure to flood etc.
2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate
3. Second floor of both Administrative Block and Main Block are not considered for issuing fitness as its Completion & Occupancy Certificate procedures are not completed yet.

Certified that the School was inspected by me on 31.05.2024 and found to be fit to conduct classes for the academic year 2024-25 for the reasons stated above.

Place : Santhipuram

Date : 31.05.2024



Signature:

Designation:


SONA O.T
PEN : 688047
ASSISTANT ENGINEER
LID & EW Section
Sreenarayanapuram Grama Panchayat
Ph: 9037528703, 04802850252